



Helm Instrument Company, Inc.  
361 West Dussel Drive  
Maumee, Ohio 43537 USA  
419/ 893-4356  
Fax: 419/ 893-1371  
www.helminstrument.com

# HELM MODEL PTM-1 STRAIN GAGE I/O MODULE

## *User Manual*



## **HELM MODEL PTM-1 STRAIN GAGE I/O MODULE** **INSTALLATION/OPERATING INSTRUCTIONS**

The following provides installation and operating instructions for the Helm Model PTM-1 Strain Gage I/O Module, when used with a full-bridge strain gage sensor or load cell.

### 1.) **General Description**

The Helm Model PTM-1 Strain Gage I/O Module is shown in Helm drawing E1096i01. It is a compact 1-channel strain gage signal conditioning module, for use with "Full Bridge" strain gage load cells and sensors. The internal circuitry includes signal filtering, amplification, calibration, auto-zero, and peak hold functions. Inputs include full-bridge strain gage sensor excitation and signal connections, plus 24 VDC power and external timing. Outputs include a scaled track and peak 0 –10 VDC analog voltage signal. The module allows for ease of installation and stable load cell signal output in industrial applications. As the drawing shows, the plastic housing for the module is configured for DIN rail mounting.

### 2.) **Module Mounting**

The Model PTM-1 Module should be snapped securely into a DIN mounting rail inside an electrical panel. The module should be located so that it is physically isolated (no closer than 1 foot) from AC power lines, relays, or motors. This is to prevent the possible bad effects of electromagnetic "noise" generated by such devices. The module should be located close to a power supply of 24 VDC, and also close enough to the sensor or load cell to make proper wiring connections.

### 3.) **Electrical Wiring and Module Specifications**

Electrical wiring connections and specifications for the module are shown in Helm drawing E1096w03. The various connections are very simple, and are outlined below.

#### **INPUTS**

##### **24 VDC Power Input**

24 VDC power input is connected at the 3 screw terminals at the bottom of the module.

##### **Strain Gage Sensor Input**

The strain gage sensor wires are connected at the orange 5-pole Weidmuller connector at the bottom of the module. Connections include "± Gage", "± Signal", and "Shield". For ease of wiring at the connector, it can be removed from the module while making the 5 connections at the screw terminals.

## **HELM MODEL PTM-1 STRAIN GAGE I/O MODULE** **INSTALLATION/OPERATING INSTRUCTIONS**

**Please note that for a Helm compression load cell (excluding LC-Series calibration load cells), the “+ Gage (Green)” and “- Gage (Black)” connections should be reversed from those shown on the drawing. This is in keeping with the Helm load cell wiring convention, and allows for positive output in compression.**

### External Timing Input (“Peak Look Window”)

The PTM-1 module requires a 24 VDC external timing input (“Peak Look Window”) for each machine cycle to be monitored. Three main types of external timing input signals can be used, including dry contact, prox probe, or PLC output. Wiring connections for the particular timing input device are made at the 3 “Cam” screw terminals at the bottom of the module.

## **OUTPUTS**

### 0-10 VDC Signal Output (“Track and Peak”)

The module signal output connections are made at the 3 screw terminals at the top. For 0-10 VDC analog voltage “Track” output, use the “Track” and “Acom” connections. This provides an instantaneous output voltage signal scaled to the sensor input. For 0-10 VDC analog voltage “Peak” output, use the “Peak” and “Acom” connections. This provides a peak output voltage signal for each cycle that is scaled to the sensor input. Based on the external timing function for each machine cycle, the peak signal value is held in memory at the end of each cycle, and then reset to zero at the start of each new cycle.

These output connections typically go to a PLC or similar device, where the conditioned sensor or load cell output signal can be used to drive an operator display or meter to show actual calibrated tonnage. If desired by the user, “High/Low Alarm” functions can be programmed at the PLC.

## 4.) Initial Set-Up and Calibration

### Zero Balance

After the proper wiring connections are made, the module should be set up by connecting a good quality voltmeter to the 0-10 VDC analog voltage “Track” output terminals (“Track” and “Acom”). There should be no load on the sensor, and the external timing input signal should be off (between cycles). Set the small 3-position toggle switch at the top of the module to the center “Off” position. Adjust the small “Bal” (Balance) pot below the switch so that the voltmeter reads 0.00 volts. This electronically “zero balances” the sensor or load cell to the module circuit.

## **HELM MODEL PTM-1 STRAIN GAGE I/O MODULE** **INSTALLATION/OPERATING INSTRUCTIONS**

### Calibration

With the voltmeter still connected to the module, move the small toggle switch to the upper "Cal" (Calibration) position. The voltmeter will now show the "Shunt Calibration Number" as a voltage, based on a fixed 499K shunt resistor in the module. This voltage "Calibration Number" can be adjusted up or down, if needed, by turning the small "Gain" pot above the switch.

For some applications, such as the case with a pre-calibrated load cell, the proper "Calibration Number" is known in advance. Typically, such a value is expressed in percent, i.e., for example, 50% at 499K at rated capacity. In order to enter such a percent "Calibration Number", first convert it from percent to voltage. This is done by multiplying the percent value times the Helm standard of 2.667 volts "Track Output" at 100% full scale. For this example, that would be  $50\% \times 2.667 \text{ V} = 1.333\text{V}$ . The "Gain" pot should then properly be adjusted so that the voltmeter reads 1.333V. In that condition, and with the module running in normal mode, the "Track Output" and "Peak Output" sensor signals will be scaled at  $2.667 \text{ V} = 100\%$  full scale. If a different scaling is desired, the "Gain" pot can simply be adjusted up or down, to achieve the proper full scale output value up to a maximum of 10 VDC.

For other applications, such as the case with bolt-on strain gage sensors (Helm Model HT-400 Strain Gain), the proper "Calibration Number" may not necessarily be known in advance. For that case, the machine to which the sensors are mounted should be "field calibrated", using portable calibration load cells and instrumentation to verify the actual developed tonnages. During that procedure, the "Gain" pot on the module should be adjusted as needed to achieve the desired "Track Output" and "Peak Output" scaled values to drive the display meter. The corresponding voltage "Calibration Number" can be read on the voltmeter with the toggle switch in the "Cal" position.

When the "Zero Balance" and "Calibration" procedures are completed, the toggle switch should be set to the lower "A/Z" (Auto-Zero) position for normal operation.

### External "Peak Look Window" Timing

As stated above, an external timing signal input ("Peak Look Window") is required for each machine cycle to be monitored. This 24 VDC signal can be generated by a dry contact, prox probe, or PLC output. In general, the timing signal should start shortly before the forming load begins for the new cycle, and should end shortly after the forming load is finished. In effect, the timing signal "tells" the module when to "look" at the forming signal for each cycle, and to capture the "Peak" load value within that time frame. This occurs when the timing signal is "On". When the timing signal is "Off", and provided that the toggle switch is set to the lower "A/Z" (Auto-Zero) position, the "Auto-Zero Balance" function is turned on to maintain a proper zero balance reference. "Auto-Zero" is turned off when the timing signal is on, and load is occurring. At the start of

## **HELM MODEL PTM-1 STRAIN GAGE I/O MODULE** **INSTALLATION/OPERATING INSTRUCTIONS**

each new timing signal, a “Peak Reset” function happens to reset the previous peak value, and to start the “Peak Capture” for the new machine cycle.

### 5.) Normal Operation


After the set-up and calibration have been completed, the toggle switch should be set to the lower “A/Z” (Auto-Zero) position for normal operation. This allows the “Auto-Zero Balance” function to operate between active load cycles, maintaining a proper zero reference for accurate signal output values.

As the machine is cycled and load is placed on the sensor or load cell, the module will generate scaled “Track Output” and “Peak Output” analog DC voltage signals. The “Track Output” is simply the instantaneous signal output from the sensor, and is always on. The “Peak Output” is controlled by the external timing signal with a “Peak Capture” function, and is the overall peak signal output from the sensor for a current cycle. It is held in memory at the end of each timing signal (“Peak Look Window”), and reset to zero by a “Peak Reset” function at the start of the next timing signal for the new cycle.


In terms of signal output scaling, the Helm standard is 2.667 VDC = 100% full scale capacity. Load values between no load and 100% capacity will yield a proportional output signal between the particular minimum and maximum output points. As stated above, if desired, the signal output scaling can be adjusted to any value up to 10 VDC = 100% full scale by means of the “Gain” pot.

# TIMING DIAGRAM - STAMPING


"TRACK OUT" SIGNAL  
(0-4V DC)



"CAM" SIGNAL  
(+24V DC)





"PEAK OUT" SIGNAL  
(0-4V DC)



THIS DRAWING AS WELL AS THE SUBJECT MATTER THEREON IS EXCLUSIVE PROPERTY OF HELM INSTRUMENT CO., INC. IT IS TO BE TREATED BY YOU AS CONFIDENTIAL, PROPRIETARY INFORMATION. THE DRAWING OR SUBJECT MATTER THEREOF SHALL NO BE DUPLICATED OR DISCLOSED WITHOUT THE EXPRESS WRITTEN CONSENT OF HELM INSTRUMENT CO., INC.

SCALE:	NONE	DESIGNED BY:	N.F.N.	DRAWN BY:	M.H.L.	
DATE:	5/29/97	CHECKED BY:	N.F.N.	APPROVED BY:	R.J.G.	
TITLE:	TYPICAL TIMING DIAGRAM, STAMPING (HELM)					
DRAWER:					DRAWING NUMBER:	T-3097-11

# *HELLM Model "PTM-1" Peak-track Strain Gage I/O Module Dimensions*



THIS DRAWING AS WELL AS THE SUBJECT MATTER THEREON IS EXCLUSIVE PROPERTY OF HELM INSTRUMENT CO., INC. IT IS TO BE TREATED BY YOU AS CONFIDENTIAL, PROPRIETARY INFORMATION. THE DRAWING OR SUBJECT MATTER THEREOF SHALL NO BE DUPLICATED OR DISCLOSED WITHOUT THE EXPRESS WRITTEN CONSENT OF HELM INSTRUMENT CO., INC.

SCALE:	FULL	DESIGNED BY:	M.H.L.	DRAWN BY:	M.H.L.	
DATE:	09/17/04	CHECKED BY:	R.J.G.	APPROVED BY:	R.J.G.	
TITLE:	"PTM-1" PEAK-TRACK STRAIN GAGE I/O MODULE DIMENSIONS (HELLM)					
DRAWER:					DRAWING NUMBER:	E1096101

