



Helm Instrument Company, Inc.
361 West Dussel Drive
Maumee, Ohio 43537 USA
419/ 893-4356
Fax: 419/ 893-1371
www.helminstrument.com

HM-SCM4-WM High Resolution Strain Gage Input Module User Manual 12/6/2019



December, 2019

Force Measurement and Control Solutions

HM-SCM4-WM Operating Instructions

IMPORTANT USER INFORMATION.....	1
PREFACE.....	2
WHO SHOULD USE	2
PURPOSE OF THIS MANUAL	2
TECHNIQUES USED IN THIS MANUAL	3
PRODUCT SUPPORT	3
HARDWARE OVERVIEW.....	4
HM-SCM4-WM SPECIFICATIONS.....	4
GETTING STARTED.....	5
REQUIRED TOOLS AND EQUIPMENT	5
SETTING IP ADDRESS	5
FRONT PANEL	6
MODULE I/O CONFIGURATION.....	7
ADDING LADDER PROGRAM.....	9
MODULE INITIAL SETUP PROCEDURE.....	13
OUTPUT BITS AND CONTROLLER TAGS.....	14
NORMAL & AUTO CALIBRATION PROCEDURE.....	15
APPENDIX A: ILLUSTRATION.....	16
APPENDIX B: SYSTEM CONNECTIONS.....	17

HM-SCM4-WM Operating Instructions

IMPORTANT USER INFORMATION

Solid state equipment has operational characteristics differing from those of electromechanical equipment. “Safety Guidelines for the Application, Installation and Maintenance of Solid-State Controls” (Allen-Bradley Publication SGI-1.1) describes some important differences between solid state equipment and hard-wired electromechanical devices. Because of this difference, and also because of the wide variety of uses for solid state equipment, all persons responsible for applying this equipment must satisfy themselves that each intended application of this equipment is acceptable.

In no event will the Helm Instrument Company be responsible or liable for indirect or consequential damages resulting from the use or application of this equipment.

The examples and diagrams in this manual are included solely for illustrative purposes. Because of the many variables and requirements associated with any particular installation, the Helm Instrument Company cannot assume responsibility or liability for actual use based on the examples and diagrams.

No patent liability is assumed by Helm Instrument Company with respect to use of information, circuits, equipment, or software described in this manual.

Throughout this manual we use notes to make you aware of safety considerations.

HM-SCM4-WM Operating Instructions

PREFACE

Read this preface to become familiar with the rest of this manual. This preface covers the following topics:

- Who should use this manual
- The purpose of this manual
- Terms and abbreviations
- Conventions used in this manual
- Helm Instrument support

WHO SHOULD USE?

Use this manual if you are responsible for the design, installation, programming, or maintenance of an automation control system that uses Allen-Bradley small logic controllers.

You should have a basic understanding of electronic process control and be able to interpret the ladder logic instructions required to generate the electronic signals that control your application. If you do not, contact your local Helm representative for the proper training before using this product.

PURPOSE OF THIS MANUAL

This manual contains the information you need to install, wire, and use the module.

HM-SCM4-WM Operating Instructions

TECHNIQUES USED IN THIS MANUAL

The following conventions are used throughout this manual:

- Bulleted lists such as this one provides information, not procedural steps.
- Numbered lists provide sequential steps or hierarchical information.

PRODUCT SUPPORT

Contact your Helm representative or call Helm direct at 419-893-4356:

- sales and order support
- product technical training
- warranty support
- support service agreements

Download up to date manuals and ladder logic files at
<http://www.helminstrument.com/manuals-and-downloads/>

Your Questions or Comments on this Manual

If you have any suggestions for how this manual could be made more useful to you, please send us your ideas.

HM-SCM4-WM Operating Instructions

HARDWARE OVERVIEW

The HM-SCM4-WM module is DIN rail mount. It is a Class 1 module.

The module can accept 4 channels of strain gage input. Maximum of 4 load cells at 350 ohms
Module configuration requires manual and user programmable setup. The module receives and stores digitally converted analog data into the PLC image table for retrieval.

HM-SCM4-WM SPECIFICATIONS

Type of input	Strain Gage (350-ohm, 700-ohm, 1100-ohm)
Input Impedance	10k
Display Resolution	Up to .0025% of full scale
Overall Module Accuracy	.01% of full scale
Number of Channels	4 (isolated)
Module Update Time	2 millisecond
A/D Conversion Method	Successive Approximation - 18 bit
Normal Mode Rejection: (between +/- input)	116DB CMRR
Amplifier Bandwidth	200 kHz

GETTING STARTED

This chapter can help you to get started using the Helm Strain Gage module. The procedures included here assume that you have a basic understanding of PLC products. You should understand electronic process control and be able to interpret the ladder logic instructions required to generate the electronic signals that control your application.

Because it is a start-up guide, this chapter does not contain detailed explanations about the procedures listed. It does, however, reference other chapters in this book where you can get more information about applying the procedures described in each step. It also references other documentation that may be helpful if you are unfamiliar with programming techniques or system installation requirements. If you have any questions or are unfamiliar with the terms used or concepts presented in the procedural steps, always read the referenced chapters and other recommended documentation before trying to apply the information.

This chapter will:

- tell you what equipment you need
- explain how to install and wire the module
- show you how to calibrate the module

REQUIRED TOOLS AND EQUIPMENT

Have the following tools and equipment ready:

- small blade screwdriver
- programming equipment (All programming examples shown in this manual demonstrate the use of Rockwell RSLogix 5000 Software).

HM-SCM4-WM Operating Instructions

GETTING STARTED CONT.


Use power supply supplied with module. Refer to wiring drawing for connections.

SETTING IP ADDRESS

Unzip hms-ip config tool
Install utility
Run utility to change IP address

Open Ladder Logic file
- copy all controller tags into project
- copy ladder logic routine "Main Program"

FRONT PANEL



Link Status Indicator Lights

OK light is on (green) when PLC communication is OK.


HM-SCM4-WM Operating Instructions

MODULE I/O CONFIGURATION

This shows the preliminary setup and operation required before the module can function in a 1756 I/O system using RSLogix5000

Adding Module to I/O Configuration


Select **Generic Ethernet Module** from *Select Module Type* window.



HM-SCM4-WM Operating Instructions

Configuration Module's Properties

From the Controller Organizer, right click on the added module and open up Module Properties windows




Type in a name for the module, select a slot number.

General: Connection Parameters

	Assembly Instance	Size
Input	100	4
Output	150	1
Configuration	3	0

Connection: Requested Packet Interval (RPI): 2.0ms



HM-SCM4-WM Operating Instructions

ADDING LADDER PROGRAM

OUTPUT BIT TAGS

Bit Tags Output	Data Type	Description
output_bits	INT	
output_bits.0	BOOL	cal mode
output_bits.1	BOOL	run mode
output_bits.2	BOOL	reset average
output_bits.3	BOOL	ch1 clear tare
output_bits.4	BOOL	ch1 tare
output_bits.5	BOOL	ch2 clear tare
output_bits.6	BOOL	ch2 tare
output_bits.7	BOOL	ch3 clear tare
output_bits.8	BOOL	ch3 tare
output_bits.9	BOOL	ch4 clear tare
output_bits.10	BOOL	ch4 tare
output_bits.11	BOOL	autocal enable ch1
output_bits.12	BOOL	autocal enable ch2
output_bits.13	BOOL	autocal enable ch3
output_bits.14	BOOL	autocal enable ch4
output_bits.15	BOOL	
set_average_count	DINT	limit 1 to 500

Run Mode Bit: When reading or downloading the module's configuration data using `Data[0].0` and `.Data[0].2`, this bit needs to be at 0. For any other operation, such as reading weigh value, leave the bit at 1.

Cal Mode: Use for diagnostics, no scale, raw A/D values.

Weigh Mode: Scaled value.

Clear Tare Offset Bit: Resets or removes tare value from module for the channel selected.

Set Tare: Set tare values.

CH1 Auto-tune: Set to known weight.

CH2 Auto-tune: Set to known weight.

CONTROLLER TAGS

Controller Tags	
auto_tare	INT
ch1_autocal_mv_v	REAL
ch1_known_weight	DINT
ch1_scale_set	DINT
ch1adtrimset	DINT
ch1average	DINT
ch1weigh	DINT
ch2_autocal_mv_v	REAL
ch2_known_weight	DINT
ch2_scale_set	DINT
ch2adtrimset	DINT
ch2average	DINT
ch2weigh	DINT
ch3_autocal_mv_v	REAL
ch3_known_weight	DINT
ch3_scale_set	DINT
ch3adtrimset	DINT
ch3average	DINT
ch3weigh	DINT
ch4_autocal_mv_v	REAL
ch4_known_weight	DINT
ch4_scale_set	DINT
ch4adtrimset	DINT
ch4average	DINT
ch4weigh	DINT
MSF1	INT
MSF2	INT
MSF3	INT
MSF4	INT
set_mv_v_ch1	REAL
set_mv_v_ch2	REAL
set_mv_v_ch3	REAL
set_mv_v_ch4	REAL

HM-SCM4-WM Operating Instructions

0

[NOP]

1

SCM4_WM_DINT	
SCM4_WM_DINT	SCM4WM1 ...
SetCalMode	output_bits.0 0
SetRunMode	output_bits.1 1
SetScaleChx	ch1_scale_set 100000
Set_mV_V_Chx	set_mv_v_ch1 2.0
SetRefChx	ch1_known_weight 100000
AutoCalEnChx	output_bits.11 0
Sample_Set	set_average_count 1
Chx_mV_V_Out	ch1_autocal_mv_v 2.0172822
set_ch_adtrim	ch1adtrimset 108000
resetaverage	output_bits.2 0
chx_tare	output_bits.4 0
chx_cleartare	output_bits.3 0
sample_rpi	sample_rate 1
auto_tare_band	auto_tare 0
getvaluein	nicktest:I.Data[0] 0
msf	msf1 0
getvalueout	ch1weigh -46

2

SCM4_WM_DINT	
SCM4_WM_DINT	SCM4WM2 ...
SetCalMode	output_bits.0 0
SetRunMode	output_bits.1 1
SetScaleChx	ch2_scale_set 100000
Set_mV_V_Chx	set_mv_v_ch2 2.0
SetRefChx	ch2_known_weight 100000
AutoCalEnChx	output_bits.12 0
Sample_Set	set_average_count 1
Chx_mV_V_Out	ch2_autocal_mv_v 2.0172822
set_ch_adtrim	ch2adtrimset 108000
resetaverage	output_bits.2 0
chx_tare	output_bits.6 0
chx_cleartare	output_bits.5 0
sample_rpi	sample_rate 1
auto_tare_band	auto_tare 0
getvaluein	nicktest:I.Data[1] 0
msf	msf2 0
getvalueout	ch2weigh 8

HM-SCM4-WM Operating Instructions

3

SCM4_WM_DINT	
SCM4_WM_DINT	SCM4WM3 ...
SetCalMode	output_bits.0 0
SetRunMode	output_bits.1 1
SetScaleChx	ch3_scale_set 100000
Set_mV_V_Chx	set_mv_v_ch3 2.0
SetRefChx	ch3_known_weight 100000
AutoCalEnChx	output_bits.13 0
Sample_Set	set_average_count 1
Chx_mV_V_Out	ch3_autocal_mv_v 2.016583
set_ch_adtrim	ch3adtrimset 108000
resetaverage	output_bits.2 0
chx_tare	output_bits.8 0
chx_cleartare	output_bits.7 0
sample_rpi	sample_rate 1
auto_tare_band	auto_tare 0
getvaluein	nicktest:I.Data[3] 0
msf	msf3 0
getvalueout	ch3weigh -4

4

SCM4_WM_DINT	
SCM4_WM_DINT	SCM4WM4 ...
SetCalMode	output_bits.0 0
SetRunMode	output_bits.1 1
SetScaleChx	ch4_scale_set 100000
Set_mV_V_Chx	set_mv_v_ch4 2.0
SetRefChx	ch4_known_weight 100000
AutoCalEnChx	output_bits.14 0
Sample_Set	set_average_count 1
Chx_mV_V_Out	ch4_autocal_mv_v 2.0186808
set_ch_adtrim	ch4adtrimset 108000
resetaverage	output_bits.2 0
chx_tare	output_bits.10 0
chx_cleartare	output_bits.9 0
sample_rpi	sample_rate 1
auto_tare_band	auto_tare 0
getvaluein	nicktest:I.Data[3] 0
msf	msf4 0
getvalueout	ch4weigh -8

(End)

HM-SCM4-WM Operating Instructions

MODULE INITIAL SETUP PROCEDURE

A complete listing of a sample ladder logic program is included at the back of this manual. Examples shown here are for reference.

All values are 0 (default) on initial start-up. This means that all alarms are disabled. You must make the following adjustments for proper operation:

- Balance sensor input(s)
- Set Calibration numbers

Follow Steps 1 and 2 for each channel.

Step 1. Balance Sensor Input

1. Set to CAL mode.
2. Set Clear Tare bit momentarily.
3. Check Raw A/D value. (131,000)
4. Set Zero Tare bit momentarily.

Step 2. Set Calibration Numbers

1. Set Scale to capacity of load cell.
2. Set mV/V to load cell specification.

Example:

100 ton load cell, 2.025 mV/V

For scale set, enter 100

For mV/V set, enter 2.025

3. Set to RUN mode.

HM-SCM4-WM Operating Instructions

OUTPUT BITS

CAL-MODE

All scale parameters are bypassed, raw a/d values, use full diagnostics

RUN MODE

Weigh values are scaled based upon scale set parameters.

RESET AVERAGE

Toggle bit, needed for first run, initializes values in memory for average.

CLEAR TARE

Toggle bit to remove offset calc. used for diagnostics.

TARE

Toggle bit to set weigh value to zero

AUTOCAL ENABLE

Set bit to run auto-cal

CONTROLLER TAGS

AUTO TARE

Used to set weigh values to zero when weigh station is at rest or idle condition (no-weight)

Set to value in counts, if weigh is within band set by counts, weigh will be set to zero

Set to zero to bypass this function

Normal setting <2> counts

AUTOCAL MV_V

Value that is updated when auto cal is used

KNOWN WEIGHT

Enter value for known weight when using auto cal

SCALE SET

Set to capacity of load cell

ADTRIMSET

Set to value on cal sticker on the side of the module

CH1-CH4 WEIGH

Current weigh value

MSF1-MSF2

Meter stabilization filter

Set value in counts, keeps weigh value from changing if weight is not moving

Normal setting 1 or 2 set to zero to bypass

SAMPLE RATE

Set to module RPI setting

Normal setting <2>

HM-SCM4-WM Operating Instructions

SET AVERAGE COUNT

Number of samples for average

Normal setting <100>

Set to 0 or 1 for no average

SET MV-V CH1-CH4

Set to values on load cell or on cal. cell certificate

NORMAL CALIBRATION PROCEDURE

1. Enter mV/V from load (set mV/V)
2. Enter capacity from load (set scale)
3. Resolution determined by scale set

EXAMPLE:

1. Enter 1,000 = 1 gram / count
2. Enter 10,000 = .1 gram / count

AUTO CALIBRATION PROCEDURE

Before running, weight must be stable and weight returns to zero when weight is removed

1. Enter known weight at chx_known_wei
2. Enter load cell capacity at scale
3. Enter 2.000 at set mv_v_chx

EXAMPLE:

1kg load cell, 500 gram known weight, for 1-gram resolution

1. Enter 1,000 at scale set
2. Enter 500 at known_weight
3. Enter 2.000 at set mv_v_chx

Toggle tare bit (no weight at start)

Apply known weight


Set autocal_enable_chx

Auto cal mv_v_v will change to correct value and weigh value will update to known weight

Clear auto cal enable

Enter auto cal mV/V at set mv_v_chx

HM-SCM4-WM Operating Instructions



THIS DRAWING AS WELL AS THE SUBJECT MATTER THEREON IS EXCLUSIVE PROPERTY OF HELM INSTRUMENT CO., INC. IT IS TO BE TREATED BY YOU AS CONFIDENTIAL, PROPRIETARY INFORMATION. THE DRAWING OR SUBJECT MATTER THEREOF SHALL NOT BE DUPLICATED OR DISCLOSED WITHOUT THE EXPRESS WRITTEN CONSENT OF HELM INSTRUMENT CO., INC.

SCALE: 2:3	DESIGNED BY: M.G.F.	DRAWN BY: M.G.F.
DATE: 12-4-19	CHECKED BY: M.H.L.	APPROVED BY: N.F.N.
TITLE: HM-SCM4-WM ILLUSTRATION (HELM INSTRUMENT CO., INC.)		
DRAWER:		DRAWING NUMBER: ILLUSTRATION

HM-SCM4-WM Operating Instructions

Customer Connections

HELM MODEL
HM-SCM4-WM

